

PeakTech® 4200 PROD-ID: P 4200

[BACK](#)

Current Clamp Adapter for Multimeter ~ 200 A AC ~ with 4mm Plugs

This clamp-adaptor are transducer, which allow to measure electrical current ACA by connection with a digital-multimeter. When measuring current with this clamp-adaptor, it is no need to break a circuit or to affect the insulation. This adaptor with a design of finger guard, ensures user operating under condition safe.

- Safety: EN 61010-1, CAT II 600 V
- Accessories: case and manual



MANUAL

[PeakTech_4200_05-2019F.pdf \(495.3 kB\)](#)

PICTURE

[4200.jpg \(65.8 kB\)](#)

ACA	200 A; $\pm 2,0 \%$ + 0,5 A (40 - 400 Hz); 1 mV/A
Conductor diameter	16 mm
Dimensions (WxHxD)	111 x 50 x 33 mm
Weight	130 g
EAN-13	4250569401114

