

PeakTech® 1020



Dieses handliche Multimeter im Taschenformat ist TÜV-GS geprüft und entspricht höchsten Sicherheitsstandards.

Als praktische Zusatzfunktionen bietet dieses Gerät eine ultrahelle LED zur Messplatzbeleuchtung bei schlechten Beleuchtungsverhältnissen und einen berührungslosen Spannungsprüfer.

Durch die Sicherungsautomatik im mA-Strombereich und die fest am Gerät angebrachten Prüfspitzen ist dieses Multimeter wartungsfrei und damit ideal für den Einsatz im Ausbildungs- und Servicebereich.

- 12 mm 3 1/2-stellige LCD-Anzeige, max. 2000
- Mit 200 mA Sicherungsautomatik
- Automatische Bereichswahl und Abschalt-automatik
- Data-Hold
- Sicherheit: TÜV/GS; EN 61010-1; CAT IV 600 V
- TÜV/GS; TÜV-Rheinland
- Zubehör: Batterien und Bedienungsanleitung



This handy pocket-size multimeter is TÜV GS tested and meets the highest safety standards.

As a practical additional feature, this unit offers an ultra-bright LED for measuring area illumination in poor lighting conditions and a non-contact voltage tester.

By the automatic fuse in the mA-current range and the probes affixed to the device, this multimeter is maintenance-free and therefore ideal for use in the educational and service area.

- 12 mm 3 1/2 digit LCD display, max. 2000
- With 200 mA automatic circuit breaker
- Autoranging, auto power off
- Data hold
- Safety: EN 61010-1; CAT IV 600 V
- TÜV/GS; TÜV-Rheinland
- Accessories: Batteries and Manual

► SPECIFICATIONS

DCV	200 mV/2/20/200/600 V; 100 µV; +/- 1,2 % + 3 dgt.
ACV	2/20/200/600 V; 1 mV; +/- 1,0 % + 8 dgt.
DCA	200/2000 µA/20/200 mA; 0,1 µA; +/- 2,0 % + 9 dgt.
ACA	200/2000 µA/20/200 mA; 0,1 µA; +/- 2,5 % + 10 dgt.
Ohm	200 Ω/2/20/200 kΩ/2/20 MΩ; 0,1 Ω; +/- 1,2 % + 5 dgt.
Betriebsspannung / Operation voltage	2 x 1,5 V AAA Batterien / batteries
Abmessungen / Dimensions (BxHxT/WxHxD)	55 x 110 x 40 mm
Gewicht / Weight	160 g